


GEN4 FF12

FITTING INSTRUCTIONS



TEMPLATE MUST BE PRINTED AT 100% PAGE SIZE DO NOT SCALE

**DO NOT USE ACETONE ON THIS PRODUCT
DO NOT COAT WITH TRADITIONAL ANTI FOUL (SEE 7)**

FF12 Fitting Instructions

1. Determine location of lights
2. Using this template mark and drill mounting holes
3. For thru-hull cable entry, mark and drill holes as per template
4. **Apply generous amount of sealant to cable entry and screw holes**
5. Using a hand screwdriver and screws provided fix lights to vessel **HAND TIGHTEN ONLY**
6. Connect Red to + and Black to - then to a switched and fused 12 or 24 Volts DC power source
7. Lights should be coated with Prospeed Clear Coat or Lightspeed after install and cleaned regularly, recoat at lift out.

(Fuse size will be determined by number of lights - allow 2 amps per light @ 12 Volts DC)

**WARRANTY WILL BE VOIDED IF SEALANT IS APPLIED ANYWHERE
EXCEPT THE CABLE ENTRY & SCREW HOLES**